

TEMS Pocket CDMA 8.0

External Release Note

© Ascom Network Testing AB All rights reserved.

No part of this document may be reproduced in any form without the written permission of the copyright holder.

TEMS is a trademark owned by Telefonaktiebolaget L M Ericsson, Sweden. All other trademarks belong to their respective owner.

The contents of this document are subject to revision without notice due to continued progress in methodology, design and manufacturing. Ericsson shall have no liability for any error or damage of any kind resulting from the use of this document.

Contents

1.	About This Release.....	4
2.	Feature Description & Enhancements	4
2.1.	General New Features.....	4
3.	Known Bugs and Limitations.....	5
3.1.	Other limitations	5
4.	Contact Information.....	5

1. About This Release

TEMS Pocket CDMA 8.0 is a product that introduces new features as described in the text below.

This product introduces the TEMS Pocket tool on the platform CDMA on Windows Mobile.

2. Feature Description & Enhancements

Please study the TEMS Pocket CDMA 8.0 Technical Product Description, 221 02-FAP 901 0946 Rev A to read details about the general features in TEMS Pocket CDMA 8.0.

2.1. General New Features

- TEMS Pocket Support for a new platform, CDMA
- Smartphone implementation, HTC TouchPro with Windows Mobile
- Graph monitors to view trends in networks
- Logging of network events with direct indication and counters to summarize information
- Strong support for mobile behavior control, making it a powerful test tool for RF engineers
- Integration with TEMS Investigation to create a complete network monitoring solution with cost-effective network data collection
- Support for 1xEVDO (CDMA) 850/1900 MHz
- Command Sequence; Voice, HTTP, FTP, Ping testing
- User designed graph views

3. Known Bugs and Limitations

This section includes known bugs and limitations in TEMS Pocket CDMA 8.0.

ID	Summary	WoR
9102 32287 32378	TEMS Investigation 10.0 cannot show application information or finger information from TEMS Pocket CDMA 8.0 log files. However, the data is logged.	

WoR – Workaround exists. Please contact TEMS Support for further information.

3.1. Other limitations

None at this time.

4. Contact Information

For customer support contact information, please visit our website on the Internet: www.ascom.com/networktesting